

Oil Field Environmental Incident Summary

Incident: 20141208140836 **Date/Time of Notice:** 12/08/2014 14:08

Responsible Party: RIM OPERATING, INC.

Well Operator: RIM OPERATING, INC.

Well Name: CORPS OF ENGINEERS 31-10

Field Name: BAKER

Well File #: 11920

Date Incident: 12/7/2014 **Time Incident:** 07:30

Facility ID Number:

County: MCKENZIE

Twp: 153

Rng: 101

Sec: 10

Qtr:

Location Description:

Submitted By: Troy Johnson

Received By:

Contact Person: Jason Rouse
5 INVERNESS DRIVE EAST
ENGLEWOOD, CO 80112

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained in Dike: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	25	Barrels	24	Barrels		
Brine	50	Barrels	45	Barrels		

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

Not Applicable

Areal Extent:

Potential Environmental Impacts:

Not Applicable

Action Taken or Planned:

A less appealing fixed height pipe stand was installed in place of the shinny new adjustable variety.

Wastes Disposal Location: The recovered fluids were put in tanks on our location. We will clean and process the fluids at our facility.

Agencies Involved: NDIC - Richard Dunn

Updates

Date: 12/9/2014 ***Status:*** Reviewed - Assigned to Other Agency

Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release, due to an on-location valve/pipeline leak, remained on location within the diking according to the report. NDIC retains oversight.